Axle Combi

Tail Lift

Rear Suspension



VEHICLE INSPECTION REPORT

SM71HDF

6x2

Air

Cantilever

DAF CF 320

Cat: N				
Inspection				

Vehicle

VAT	Plus VAT
V5	Present

Details

15/02/2022	VIN	XLRASM4700G384003
2022	Body Style	Curtainside
138,340 Km Not Warranted	MOT Due	06/11/2025
	Cab Type	DAY CAB
Diesel	Gearbox	AUTOMATIC
WHITE		
	2022 138,340 Km Not Warranted Diesel	2022 Body Style 138,340 Km Not Warranted Cab Type Diesel Gearbox

*WARNING LIGHT ON DASH**MILEAGE RECORDED IN MILES & KM* REAR LIFT, Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair.

Tyres NSF

NSR

OSF OSR

Spare

Features

Park assist camera

· Air conditioning

Photos











