

VEHICLE INSPECTION REPORT

C261884

DON BUR CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2008	Colour	BLUE	Axle Combi	Tri
Year	2008	VIN	SPPM38GR8L053652	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

ROR AXLES, RAISE & LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



