

VEHICLE INSPECTION REPORT

DP66XCZ

Nissan Navara 2.3 dCi 190

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 10/01/2017

Year 2017

Mileage 75,164 Miles Not Warranted

Fuel Type Diesel

Colour BLACK

VIN VSKCTND23U0046647

Body Style Pickup Double Cab

MOT Due 19/12/2025

CAP Clean £8,225.00

CAP Average £6,975.00

CAP Below £5,300.00

Gearbox MANUAL

Gears 6

AD BLUE, E/MIRRORS, TOW BAR, SPARE WHEEL, TALLGATE ROLLER, KEY INOPERABLE.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing osf
Poor Previous Repair
Paint Flake



3: Door osf
Poor Previous Repair
Rippled UpTo 30%



4: Qtr Panel nsr
Dented
Over 30mm

Interior

Carpet Condition		-	Upholstery Condition		-
Seat Condition		-	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	